ECO PRO

CCAP

Filter Replacement Guide

Proper maintenance of your advanced CCAP (Clean Cabin-Air Pressurizer) is required to maintain healthy cab-air quality with minimal repair/maintenance cost. The CCAP provides optimal air quality in the most extreme environments. All single-seat cabs use the same system. There are currently 4 filter options available. Follow guidelines.

RECOMMENDED SERVICE INTERVALS

PART NUMBER	VACUUM	BLOW OUT	REPLACEMENT
ECO9990	250 hours	Never	Every 1,000 hours
ECO9999	250 hours	Never	Every 1,000 hours
ECO9990NH3*	250 hours	Never	Every 500 hours
ECO9999NH3*	250 hours	Never	Every 500 hours

* NH3 ammonia stage added to minimize hazardous contaminants from cab air

WHY REPLACE FILTERS?

+ Keep cab air fresh (removes organic odors)
+ Plugged filters kill motors (Not warrantable)
+ Required 2,000hr replacement (Maximum warrantable interval)

WHEN TO REPLACE FILTERS?

+ Recommended service intervals
+ Smell, odor or symptom contaminant is detected
+ Fresh air drops below 17CFM (US code requirement)

DO NOT BLOW OUT FILTER

VACUUM ONLY

ECOPRO HQ: 2443 W 12th Street, Suite 6, Tempe, AZ 85281
ecoprousa.com

(602) 820-5143 // (855) ECO-PRO2